



CA C#

Practitioner's Docket No. GR 98 P 5874 P

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent. No. : 6,798,040 *B2*
Applicant : Daniel Reznik
Issued : Sep. 28, 2004
Art Unit : 2822
Examiner : Ida M. Soward
Title : Power Semiconductor Switch
Docket No. : GR 98 P 5874 P
Customer No. : 24131

Certificate
OCT 22 2004
of Correction

Commissioner for Patents

P.O. Box 1450,

Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR APPLICANT'S MISTAKE (37 C.F.R.1.323)

1. It is noted that an error appears in this patent of a
(X) clerical () typographical () minor

Nature or character, as more fully described below. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

2. Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.
3. The exact page and line number where the error occurs in the application file are:

The related U.S. application data is missing from the first page of the original certified English translation filed on November 7, 2001 in the U.S. Patent Office.

4. Please send the Certificate to:

Name : LERNER AND GREENBERG, P.A.

Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

5. Please pay the fee of \$ 100.00, as required by 37 CFR 1.20(a), as follows:

X Enclosed is a credit card form for \$100.00.

Werner H. Stemer
WERNER H. STEMER (REG. NO. 34,956)

Oct. 14, 2004
DATE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,798,040 B2
ISSUED : Sep. 28, 2004
INVENTOR(S) : Daniel Reznik

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Item [63] should read as follows:

Continuation of application No. PCT/DE99/03836, filed on Dec. 1, 1999.

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,798,040

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 25 2004

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,798,040 B2
ISSUED : Sep. 28, 2004
INVENTOR(S) : Daniel Reznik

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Item [63] should read as follows:

Continuation of application No. PCT/DE99/03836, filed on Dec. 1, 1999.

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,798,040

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 25 2004